

<b>Lone Star</b>		<b>RM228D-256-100</b>		
<b>Qty of Cwts</b>	<b>Cwt position * on crank arm</b>	<b>ECB, lbs. @ 100" stroke at position</b>	<b>ECB, lbs. @ 82" stroke at position</b>	<b>ECB, lbs. @ 65" stroke at position</b>
<b>Counterweight No.: 7 (2 bolts)</b>		<b>Dead weight/each: 1,653 lbs</b>		
cranks only		9,882	11,668	14,354
4	14	11,882	14,057	17,327
4	20	12,740	15,081	18,602
4	30	14,169	16,788	20,725
4	40	15,598	18,495	22,849
4	50	17,027	20,202	24,973
4	60	18,456	21,908	27,097
4	70	19,885	23,615	29,221
4	73	20,314	24,127	29,858
2	14	10,882	12,863	15,841
2	20	11,311	13,375	16,478
2	30	12,025	14,228	17,540
2	40	12,740	15,081	18,602
2	50	13,454	15,935	19,663
2	60	14,169	16,788	20,725
2	70	14,884	17,641	21,787
2	73	15,098	17,898	22,106